

Permit Number	Phone Sys. Num.	Street Address	Inspection Code - Description	Insp. Num.	Inspector Name	Inspection Results	Inspection Result Comment
PRAD202301146	3020	1330 E Rosemeade Pkwy, Carrollton, Tx 75007	PRC200081 - Plumbing Top Out/Energy-Commercial	1700	Raymond Davis	Partial Pass	For roof drains only.
PRAS202305316	3040	1435 Bradley Ln, Carrollton, Tx 75007	PRC200025 - Building Framing- Commercial	1901	Michael Serna	Passed w/ Notes	Ok to proceed with electrical and equipment installation. Electrical permit PREL202306769 must pass and close to close final for this permit
PREL202307607	4062	2912 Lockwood Dr, Carrollton, Tx 75007	PRC200041 - Electrical/Energy Final-Residential	3201	David C. Garcia	Failed	1.breakers not labeled at panel 2.need wp cover at tv outlet
PREL202400679	3064	2503 Nature Bend Ln, Carrollton, Tx 75006	PRC200040 - Electrical Rough/Energy-Residential		Angel Galvan	Passed	
	4062		PRC200041 - Electrical/Energy Final-Residential		Angel Galvan	Passed	
	2010]	PRC200116 - Underfloor Electrical	13101	Angel Galvan	Passed	
PREL202400727	3064	1408 Palo Duro Dr, Carrollton, Tx 75007	PRC200040 - Electrical Rough/Energy-Residential		Angel Galvan	Passed	
	4062		PRC200041 - Electrical/Energy Final-Residential	3200	Angel Galvan	Passed	
	2010]	PRC200116 - Underfloor Electrical	13100	Angel Galvan	Passed	
PREL202400862	3064	1903 Vista Oaks Dr, Carrollton, Tx 75007	PRC200040 - Electrical Rough/Energy-Residential	1600	Angel Galvan	Passed	
PRLA202304352	1024	1413 Grimes Dr, Carrollton, Tx 75010	PRC200066 - Irrigation System/B.F.P. Final-Residential		Raymond Davis	Passed	
PRLA202307382	7000	2029 Stradivarius Ln, Carrollton, Tx 75007	PRC200140 - General Site Follow- Up (7000)	15000	Craig Whelan	Passed	
PRLA202307383		2031 Stradivarius Ln, Carrollton, Tx 75007	PRC200140 - General Site Follow- Up (7000)	15000	Craig Whelan	Passed	
PRMH202400473	4004	2414 Meadow Creek Dr, Carrollton, Tx 75006	PRC200062 - Hvac/Energy Final- Residential	3401	Hector Romero	Passed	
PRMH202400752		2331 Stone Glen Ln, Carrollton, Tx 75007	PRC200062 - Hvac/Energy Final- Residential	3400	Hector Romero	Passed	
PROA202400170	4064	2244 Luna Rd, Suite:150, Carrollton, Tx 75006	PRC200076 - Occupancy Application: O.A.; Sign/Zoning/Construction Code Final	9503	Hector Romero	Passed	



Permit Number	Phone Sys. Num.	Street Address	Inspection Code - Description	Insp. Num.	Inspector Name	Inspection Results	Inspection Result Comment
PROA202400691		Suite:320, Carrollton, Tx 75006	PRC200076 - Occupancy Application: O.A.; Sign/Zoning/Construction Code Final		Hector Romero	Passed	
PROA202400790		Suite:496, Carrollton, Tx 75006	PRC200076 - Occupancy Application: O.A.; Sign/Zoning/Construction Code Final		Hector Romero	Passed	
PROA202400820		Suite:110, Ćarrollton, Tx 75007	PRC200076 - Occupancy Application: O.A.; Sign/Zoning/Construction Code Final		Hector Romero	Passed	
PROA202400825		Carrollton, Tx 75010	PRC200076 - Occupancy Application: O.A.; Sign/Zoning/Construction Code Final	9500	Michael Serna	Passed w/ Notes	release sent
PROA202400843		Suite:330, Carrollton, Tx	PRC200076 - Occupancy Application: O.A.; Sign/Zoning/Construction Code Final	9500	Hector Romero	Passed	
PROA202400888		Suite:201, Carrollton, Tx	PRC200076 - Occupancy Application: O.A.; Sign/Zoning/Construction Code Final	9500	Michael Serna	Passed w/ Notes	release sent
PRPL202305997	1023	2425 Mc Coy Rd, Carrollton, Tx 75006	PRC200018 - Backflow Install/Replacement	5600	Raymond Davis	Passed	
PRPL202305998		3210 Furneaux Ln, Carrollton, Tx 75007	PRC200018 - Backflow Install/Replacement	5600	Raymond Davis	Passed	
PRPL202307502	1036	4206 North Cliff Dr	PRC200000 - Plumbing Work Final		Raymond Davis	Failed	Need pictures of water line installation. Please upload to the permit and reschedule the inspection.
					Raymond Davis	Passed	
	1038		PRC200163 - Double Check Valve Install		Raymond Davis	Passed	
PRPL202400108	1023	1006 S Maryland St, Carrollton, Tx 75006	PRC200018 - Backflow Install/Replacement	5601	Gregory Smith	Passed	
PRPL202400397	4021	2605 Creekway Dr, Carrollton, Tx 75010	PRC200122 - Water Heater Final		Gregory Smith	Passed	
PRPL202400641	1036	3801 Spring Hollow Dr, Carrollton, Tx 75007	PRC200000 - Plumbing Work Final	13000	Gregory Smith	Failed	1. No pictures of work or video of water test submitted for inspection. 2. No Under Slab Backfill Letter has been submitted. This is not an engineer's or compaction letter, and must be provided for EVERY under slab plumbing repair. If you need assistance, call our service desk and speak to one of our permit techs.



Permit Number	Phone Sys. Num.	Street Address	Inspection Code - Description	Insp. Num.	Inspector Name	Inspection Results	Inspection Result Comment
PRPL202400646	4021	2022 White Ash Rd, Carrollton, Tx 75007	PRC200122 - Water Heater Final		Gregory Smith	Passed	
PRPL202400706		1109 Apache Lake Dr, Carrollton, Tx 75010	PRC200122 - Water Heater Final		Gregory Smith	Passed	
PRPL202400805	1037	1007 E Alan Ave, Carrollton, Tx 75006	PR00026 - Gas Work Final- Residential		Gregory Smith	Passed	ok to restore
PRPL202400848		1745 Hayden Dr, Suite:140, Carrollton, Tx 75006	PRC200164 - Gas Work Final- Commercial	16300	Raymond Davis	Passed w/ Notes	Released
PRPL202400850		1745 Hayden Dr, Suite:150, Carrollton, Tx 75006	PRC200164 - Gas Work Final- Commercial	16300	Raymond Davis	Passed w/ Notes	Released
PRPL202400869	1036	2702 Devonshire Dr, Carrollton, Tx 75007	PRC200000 - Plumbing Work Final		Gregory Smith	Passed	
	1034		PRC200148 - Under Slab Excavation/Backfill Verification		Gregory Smith	Passed	
PRPL202400870	1036	1922 E Branch Hollow Dr, Carrollton, Tx 75007	PRC200000 - Plumbing Work Final	13001	Gregory Smith	Passed	
PRPL202400880		1617 E Crosby Rd, Carrollton, Tx 75006	PRC200000 - Plumbing Work Final		Raymond Davis	Passed	
PRPL202400881	4021	2101 Hunters Ridge, Carrollton, Tx 75006	PRC200122 - Water Heater Final		Gregory Smith	Passed	
PRPL202400900	1036	4010 Province Dr, Carrollton, Tx 75007	PRC200000 - Plumbing Work Final		Gregory Smith	Failed	Please submit a signed Virtual Inspection Cert form. This can be found on our website or with your permit.
				13001	Gregory Smith	Passed	
PRPO202306177	1012	2205 Longwood Dr, Carrollton, Tx 75010	PRC200084 - Pool Deck Bonding/Setback	10101	Michael Serna	Passed w/ Notes	corrections made. pictures sent, uploaded
PRRE202307371	1010	1916 Camden Way, Carrollton, Tx 75007	PRC200042 - Electrical Service	6703	David C. Garcia	Not Ready	need to pay re-inspection fee and reschedule for next business day 1.printed city stamped plans required on site
	6010		PRC200106 - Solar System Final		David C. Garcia	Not Ready	need to pay re-inspection fee and reschedule for next business day 1.printed city stamped plans required on site
PRRE202400353	1010	2201 Rockwood Dr, Carrollton, Tx 75007	PRC200042 - Electrical Service		David C. Garcia	Not Ready	1.canceled by contractor
	6010]	PRC200106 - Solar System Final	12400	David C. Garcia	Not Ready	1.canceled by contractor



Permit Number	Phone Sys. Num.	Street Address	Inspection Code - Description	Insp. Num.	Inspector Name	Inspection Results	Inspection Result Comment
PRRN202208506	4040		PRC200026 - Building/Energy Final- Commercial	4301	Michael Serna	Passed w/ Notes	final release sent
PRRN202306639	3040		PRC200025 - Building Framing- Commercial	1902	Angel Galvan	Passed w/ Notes	Walls covered and never inspected, Spoke to chief inspector and he said it's ok
	3030		PRC200030 - Hvac Rough/Energy- Commercial	1104	Angel Galvan	Passed	
	4030		PRC200032 - Hvac/Energy Final- Commercial	3300	Angel Galvan	Passed	
PRRN202307323	4062		PRC200041 - Electrical/Energy Final-Residential	3200	Michael Serna	Not Ready	
PRRN202400042	3000	Carrollton, Tx 75006	PRC200131 - General Follow-Up (3000)		Raymond Davis	Passed w/ Notes	The requirements have been met for the Occupancy Applications to be issued for the first floor. The following items must be addressed, the 2nd floor is not to be occupied until permits have been approved and inspections performed to allow Certificates of Occupancy to be granted. The following work must be done within 5 days, a follow-up inspection is scheduled for 2/22/2024, if work is not complete citations will be issued. 1. The shower and the water heater in the 2nd floor northeast corner suite must be removed and the lines capped. 2. The bathroom with the shower stall at the east end of the 2nd floor hallway must be removed (toilet, lavatory, and shower) all lines capped. 3. The water heater and shower in Shower Room 1 on the 2nd floor must be removed. 4. The shower in Bathroom 2 on the 2nd floor must be removed and the lines capped. 5. The shower in Bathroom 1 on the 2nd floor must be removed and the lines capped. 6. The plumbing and electrical in the kitchen on the 2nd floor must be removed and lines capped.
PRSF202303347	4063	2533 Liverpool Ln, Carrollton, Tx 75010	PRC200023 - Building/Energy Final-Residential		Michael Serna	Passed w/ Notes	final release sent
	1028		PRC200124 - Water Meter Pre- Installation R.O.WResidential		Michael Serna	Passed w/ Notes	meter already in place
PRSG202300946			PRC200178 - Real Estate Sign Annual	11100	Hector Romero	Failed	Permit for real estate sign expired, remove sign or renew permit