



## DAILY INSPECTION RESULTS

As of Thursday, February 29, 2024 6:00 PM

Permit Number	Phone Sys. Num.	Street Address	Inspection Code - Description	Insp. Num.	Inspector Name	Inspection Results	Inspection Result Comment
PRAD202301146	2010	1330 E Rosemeade Pkwy	PRC200116 - Underfloor Electrical	13100	David C. Garcia	Passed w/ Notes	1.floor boxes - 2nd floor mezzanine
PRAD202305715	4063	1828 Melton Dr	PRC200023 - Building/Energy Final-Residential	4400	Michael Serna	Passed w/ Notes	final release sent
	4062		PRC200041 - Electrical/Energy Final-Residential	3200	Michael Serna	Passed w/ Notes	release sent
PRAS202306286	4063	1413 Barclay Dr	PRC200023 - Building/Energy Final-Residential	4400	Michael Serna	Failed	permit PREL202306316 failed and must pass before building final. inspection not performed
PRAS202307280	1091	4729 Holland Ln	PRC200103 - Sign, Pier/Setback/Electrical Underground Ungr.	12100	Michael Serna	Passed w/ Notes	plumbing for pool cut to accommodate posts for pergola
PRAS202400146	2001	1915 Glen Hill Dr	PRC200155 - Engineer's Letter-Residential	4600	Melvin Moreira	VOID	
PRAS202400788	3066	2204 Jamestown Ct	PRC200022 - Building Framing-Residential	2000	Angel Galvan	Failed	no answer at door at 9:12 am
	4063		PRC200023 - Building/Energy Final-Residential	4400	Angel Galvan	Failed	no answer at door at 9:12 am
	1091		PRC200103 - Sign, Pier/Setback/Electrical Underground Ungr.	12101	Angel Galvan	Failed	no answer at door at 9:12 am
					12102	Angel Galvan	Passed
PRBD202205065	4020	1865 Arbor Creek Dr, Carrollton, Tx 75010	PRC200033 - Plumbing/Energy Final-Commercial	2901	Gregory Smith	Passed	
PRDR202300212	1053	1725 Sandy Lake Rd	PRC200077 - Paving Onsite-Commercial	9600	David C. Garcia	Passed	
PRDR202304883	5020	2903 Mesquite Dr	PRC200036 - Drive Approach/Barrier Free Ramp-Residential	6401	David C. Garcia	Failed - Add Penalty	1.concrete poured with no approved inspection
PREL202306316	4062	1413 Barclay Dr	PRC200041 - Electrical/Energy Final-Residential	3200	David C. Garcia	Failed	1.outlets not working and not type TR/WR 2.no access to panel
PREL202400309	3064	2038 Embassy Way	PRC200040 - Electrical Rough/Energy-Residential	1600	Angel Galvan	Passed	
	4062		PRC200041 - Electrical/Energy Final-Residential	3200	Angel Galvan	Passed	
	1010		PRC200042 - Electrical Service	6700	Angel Galvan	Passed	



**DAILY INSPECTION RESULTS**  
As of Thursday, February 29, 2024 6:00 PM

Permit Number	Phone Sys. Num.	Street Address	Inspection Code - Description	Insp. Num.	Inspector Name	Inspection Results	Inspection Result Comment
PREL202400635	4010	4101 International Pkwy	PRC200029 - Electrical/Energy Final-Commercial	3100	David C. Garcia	Passed	
PREL202400926	1010	1700 E Belt Line Rd	PRC200042 - Electrical Service	6700	Angel Galvan	Failed	Electrician required on site, no electrician at 8:46 am
PRFR202305905	4002	1720 E Jackson Rd	PRC200050 - Fire Marshal Final	7400	Lynn Harpold	Passed	
PRFR202306191		2700 Old Denton Rd, Suite: 104	PRC200050 - Fire Marshal Final	7400	Lynn Harpold	Passed	
PRLA202400550	1024	2557 Hampstead Ln	PRC200066 - Irrigation System/B.F.P. Final-Residential	8600	Gregory Smith	Passed	
PRLA202400882		2541 Hampstead Ln	PRC200066 - Irrigation System/B.F.P. Final-Residential	8600	Gregory Smith	Passed	
PRLA202400883		2544 Hampstead Ln	PRC200066 - Irrigation System/B.F.P. Final-Residential	8600	Gregory Smith	Passed	



## DAILY INSPECTION RESULTS

As of Thursday, February 29, 2024 6:00 PM

Permit Number	Phone Sys. Num.	Street Address	Inspection Code - Description	Insp. Num.	Inspector Name	Inspection Results	Inspection Result Comment
PRMH202307372	4004	2204 Norwich Pl	PRC200062 - Hvac/Energy Final-Residential	3400	Hector Romero	Failed	<p>one or more of the following pictures are missing. Please follow the guideline below.</p> <p>HVAC: Photo/Video Inspection Please follow; 1. Photo/Video Inspection Certification: <a href="https://www.cityofcarrollton.com/home/showdocument?id=26138">https://www.cityofcarrollton.com/home/showdocument?id=26138</a> 2. GUIDELINES FOR PHOTO/VIDEO INSPECTIONS FOR HVAC Located on the City of Carrollton web site: <a href="https://www.cityofcarrollton.com/departments/departments-a-f/building-inspection/my-development/inspection-services">https://www.cityofcarrollton.com/departments/departments-a-f/building-inspection/my-development/inspection-services</a> Photo/Video Inspection Certification: filled out, signed and dated The following pictures must be included if applicable to work: 1. Vent pipe from draft hood to ceiling or roof penetration 2. Air supply/make up air 3. Condensate; secondary pan, drain piping 4. Support/Strapping for unit and ductwork 5. Sealed duct and unit joints 6. Carbon monoxide detectors (installed) 7. Drip leg 8. Exterior line set insulation (UV &amp; damage protection) 9. Locking caps on condenser 10. A general location picture of the water heater 11. Name plate on Condenser showing max amperage 12. Breaker at electrical panel feeding Condenser, showing amperage and labeling 13. Need photo of interior disconnect to verify connector at back of disconnect. 14. Need photo of interior disconnect to verify wiring of surge protector if applicable.</p>
PRMH202400999			PRC200062 - Hvac/Energy Final-Residential	3400	Hector Romero	Passed	
PROA202400382	4064	2626 N Josey Ln, Suite: 107	PRC200076 - Occupancy Application: O.A.; Sign/Zoning/Construction Code Final	9500	Hector Romero	Passed	
PROA202400936		3333 Earhart Dr, Suite: 240	PRC200076 - Occupancy Application: O.A.; Sign/Zoning/Construction Code Final	9500	Hector Romero	Passed	



## DAILY INSPECTION RESULTS

As of Thursday, February 29, 2024 6:00 PM

Permit Number	Phone Sys. Num.	Street Address	Inspection Code - Description	Insp. Num.	Inspector Name	Inspection Results	Inspection Result Comment
PROA202401007		2425 Mc Iver Ln, Suite: 150	PRC200076 - Occupancy Application: O.A.; Sign/Zoning/Construction Code Final	9500	Hector Romero	Failed	1. Unable to verify electrical panel, no access due to items blocking access 2. No egress in warehouse, items throughout the warehouse blocking access to doors 3. Unable to verify outlets throughout the unit, items blocking all access.
PRPL202306530	1023	2440 N Josey Ln	PRC200018 - Backflow Install/Replacement	5601	Gregory Smith	Failed	Must provide a picture of the installed backflow device, as noted on the previous failed inspection.
PRPL202400436		1804 E Hebron Pkwy	PRC200018 - Backflow Install/Replacement	5601	Gregory Smith	Passed	
PRPL202400675		2625 Old Denton Rd, Suite: 800	PRC200018 - Backflow Install/Replacement	5600	Gregory Smith	Failed	Pictures of the work with a signed Virtual Inspection Cert form and backflow test must be submitted for inspection.
PRPL202400857	1036	1927 Kentwood Ln	PRC200000 - Plumbing Work Final	13000	Gregory Smith	Failed	Pictures of work must be submitted to the permit with a signed Virtual Inspection Cert form, found on our website.
PRPL202400911	4021	1724 Hartford Dr	PRC200122 - Water Heater Final	13600	Gregory Smith	Failed	A signed Virtual Inspection Cert form is required for all picture/video submissions
PRPL202401000		2027 Robin Hill Ln	PRC200122 - Water Heater Final	13601	Gregory Smith	Passed	
PRPL202401038		2704 Running Duke Dr	PRC200122 - Water Heater Final	13600	Gregory Smith	Passed	
PRPL202401068		3817 Cochran Dr	PRC200122 - Water Heater Final	13601	Gregory Smith	Passed	
PRPL202401071		2269 Woodcreek	PRC200122 - Water Heater Final	13600	Gregory Smith	Passed	
			PRC200148 - Under Slab Excavation/Backfill Verification	9800	Gregory Smith	Failed	Under Slab Backfill Letter (example found on our website) has not been submitted.
PRPL202401077	4021	2516 Willowdale Dr	PRC200122 - Water Heater Final	13600	Gregory Smith	Passed	
PRPL202401088		1606 Morning Dove Ct	PRC200122 - Water Heater Final	13600	Gregory Smith	Passed	
PRPL202401126	1037	1820 Willow Rd	PR00026 - Gas Work Final- Residential	16400	Gregory Smith	Failed	unable to locate meter and test gauge. please upload pictures and a virtual inspection cert form
PRPO202306223	1012	4540 La Roche Ave	PRC200084 - Pool Deck Bonding/Setback	10100	Michael Serna	Passed	
PRRE202400609	1010	1845 Melton Dr	PRC200042 - Electrical Service	6701	David C. Garcia	Passed	



## DAILY INSPECTION RESULTS

As of Thursday, February 29, 2024 6:00 PM

Permit Number	Phone Sys. Num.	Street Address	Inspection Code - Description	Insp. Num.	Inspector Name	Inspection Results	Inspection Result Comment
	6010		PRC200106 - Solar System Final	12401	David C. Garcia	Failed	1. TECL numbers required on vehicles 2. missing bond/set screws at bushings 3. photos of all attic work, rooftop raceways & bushings, interiors of all j-boxes and grounding to rails required on site for inspection 4. permit description of work indicates emergency disconnect installed - emergency disconnect not installed need to update permit to reflect this change 5. bond metal NM connector in pvc j-box
PRRN202302676	4040	2140 Hutton Dr	PRC200026 - Building/Energy Final-Commercial	4300	Reynaldo Guerrero	Passed w/ Notes	Final Engineer's letter uploaded, okay to close permit
PRRN202304115	4063	2240 Emerson Ln	PRC200023 - Building/Energy Final-Residential	4400	Michael Serna	Passed	
	3064		PRC200040 - Electrical Rough/Energy-Residential	1600	David C. Garcia	Passed	
	4062		PRC200041 - Electrical/Energy Final-Residential	3200	David C. Garcia	Passed w/ Notes	1. label bathroom outlets GFCI protected outlets
PRRN202306064	1091	4750 N Josey Ln	PRC200103 - Sign, Pier/Setback/Electrical Underground Ungr.	12100	Michael Serna	Partial Pass	Ok to cover conduit at riser for pad site
PRRN202306104	4062	1607 E Peters Colony Rd	PRC200041 - Electrical/Energy Final-Residential	3203	David C. Garcia	Failed	1. need guard at attic light lamp 2. add reducing washer to connector at back of a/c disconnect 3. stove outlet not GFCI protected 4. all required outlets not labeled GFCI protected outlet 5. garage GFCI not type TR
PRRN202307212	3040	1335 E Crosby Rd, Suite: 100	PRC200025 - Building Framing-Commercial	1900	Angel Galvan	Failed	Need MEP roughs approved prior to building framing
	4030		PRC200032 - Hvac/Energy Final-Commercial	3300	Hector Romero	Passed w/ Notes	Duct okay.
PRRN202307213	3034	1335 E Crosby Rd, Suite: 110	PRC200031 - Hvac Rough/Insulation-Commercial	1200	Hector Romero	Passed	
PRRN202307655	3066	2153 Cordoba Dr	PRC200022 - Building Framing-Residential	2000	Angel Galvan	Passed	
	3064		PRC200040 - Electrical Rough/Energy-Residential	1600	Angel Galvan	Passed	
	3063		PRC200061 - Hvac Rough/Energy-Residential	1300	Angel Galvan	Passed	



# DAILY INSPECTION RESULTS

As of Thursday, February 29, 2024 6:00 PM

Permit Number	Phone Sys. Num.	Street Address	Inspection Code - Description	Insp. Num.	Inspector Name	Inspection Results	Inspection Result Comment
PRRN202400205	3064	2625 Deep Valley Trl	PRC200040 - Electrical Rough/Energy-Residential	1601	David C. Garcia	Passed	
PRRN202400519	1902	2451 Old Denton Rd, Suite: 140	PRC200093 - Pre-Pour/Foundation-Commercial	900	Angel Galvan	Passed	
PRSF202302119	4062	1913 Espinosa Dr	PRC200041 - Electrical/Energy Final-Residential	3201	Michael Serna	Not Ready	waiting on homeowner for several required points of inspection
	1010		PRC200042 - Electrical Service	6700	Michael Serna	Passed w/ Notes	early meter release
	4004		PRC200062 - Hvac/Energy Final-Residential	3400	Michael Serna	Not Ready	waiting on homeowner for several required points of inspection
PRSF202304991	4005	4732 Gentle Glen Dr	PRC200115 - Plumbing/Energy/Utility Release Final-Residential	3000	Gregory Smith	Failed	Make sure the cleanouts are painted and all of the plumbing work is completed outside
PRSF202306071	1011	2125 Placid Dr	PRC200111 - Temporary Electric Pole/Swppp-Residential	200	David C. Garcia	Passed w/ Notes	1.release sent
PRSG202300627		1335 E Crosby Rd	PRC200178 - Real Estate Sign Annual	11100	Hector Romero	Failed	Permit for real estate sign expired, remove sign or renew permit.
PRSG202302628		2910 Belmeade Dr	PRC200178 - Real Estate Sign Annual	11101	Hector Romero	Passed	
PRSG202400184	1081	1025 W Hebron Pkwy, Suite: 120	PRC200104 - Sign/Banner	12201	Hector Romero	Passed	